IN THE UNITED STATES DISTRICT COURT FOR THE SOUTHERN DISTRICT OF TEXAS HOUSTON DIVISION

DIDE INTERCONTRICTOR

<i>IN RE</i> : INTERCONTINENTAL	§	Lead Case No. 4:19-cv-01460
TERMINALS COMPANY LLC	§	
DEER PARK FIRE LITIGATION	§	FIRST AMENDED MASTER LONG
	§	FORM COMPLAINT AND
This Document Relates to All Personal	§	JURY TRIAL DEMAND
Injury Actions As set forth in Agreed Order	§	
Governing Adoption of First Amended	§	
Master Long Form and Master Short Form	§	
Complaint for Filed Cases:	§	
	§	
Personal Injury Plaintiffs,	§	
	§	
V.	§	
	§	
Intercontinental Terminals Company, LLC,	§	
NSK Ltd. and NSK Corporation	§	

PLAINTIFFS' FIRST AMENDED MASTER LONG FORM COMPLAINT AND JURY TRIAL DEMAND

Plaintiffs in this Consolidated Action, by and through the undersigned counsel, submit this First Amended Master Long Form Complaint and Jury Trial Demand ("Master Complaint"), seeking judgment against Defendants Intercontinental Terminals Company, LLC, NSK Limited and NSK Corporation, for injuries sustained as a result of Defendants' conduct.

Plaintiffs intend this Master Complaint to achieve efficiency and economy by presenting certain common allegations and common questions of fact and law that generally pertain to all Plaintiffs in this Consolidated Action. Plaintiffs plead all Counts of this Master Complaint in the broadest sense and pursuant to all applicable laws and choice of law principles.

This Master Complaint does not necessarily include all claims asserted in all of the transferred actions to this Court. Each Plaintiff will adopt this Master Complaint and the causes of action alleged herein by and through a separate Short Form Complaint. Any individual facts,

jurisdictional allegations, additional legal claims, and/or requests for relief of an individual Plaintiff may be set forth as necessary in the Short Form Complaint filed by the respective Plaintiff. This Master Complaint does not constitute a waiver or dismissal of any allegations or claims asserted in those individual actions, and no Plaintiff relinquishes the right to amend his or her individual claims to include additional claims as discovery continues.

I. PARTIES AND SERVICE

- 1. This Master Complaint is filed on behalf of all Plaintiffs whose claims have been consolidated in Lead Case Number 4:19-cv-01460 in the Southern District of Texas.
- 2. Plaintiffs in these individual actions are citizens of the State of Texas who have suffered injuries arising out of the March 17, 2019 fire at ITC's Deer Park Facility.
- 3. Where applicable and/or necessary, this Master Complaint is also filed on behalf of Plaintiffs' spouses, children, parents, decedents, wards, heirs, and/or legally designated representatives.
- 4. Defendant, INTERCONTINENTAL TERMINALS COMPANY, LLC, is a limited liability company authorized to conduct business in the State of Texas. ITC's sole member, Mitsui U.S.A., is a New York Corporation with its principal place of business in New York. ITC operates a facility in Harris County, Texas (the "ITC Facility"). ITC maintains a corporate office at 1021 Main Street, Suite 1150, Houston, Texas 77002-6508. ITC has been served with process and filed answers in the underlying state court matters and has entered an appearance herein.
- 5. Defendant NSK CORPORATION ("NSK Corp.") is a foreign corporation located at 4200 Goss Road, Ann Arbor, Michigan 48105. NSK is incorporated under the laws of the State of Delaware, has its principal place of business in Michigan, and is authorized to conduct business in the State of Texas. NSK may be served through its registered agent, Corporation Service Company d/b/a CSC-Lawyers Incorporating Service Company at 211 E. 7th Street, Suite 620,

Austin, Texas 78701. SUMMONS IS HEREBY REQUESTED.

6. NSK, LTD. ("NSK Ltd.") is a foreign business entity located at the Nissei Building, 1-6-3 Ohsaki, Shinagawa-Ku, Tokyo, 141-8560, Japan. NSK Ltd. has sufficient business contacts with the State of Texas for the purpose of accumulating monetary profit, but does not maintain a regular place of business or a designated agent upon whom service of process may be had for causes of action arising out of such business done in the State of Texas. For these reasons, service of process is to be made pursuant to Rule 4(f), Federal Rules of Civil Procedure, by and through the Convention on Service Abroad of Judicial and Extrajudicial Documents in Civil or Commercial Matters, done at The Hague, November 15, 1965. 20 U.S.T. 361, T.I.A.S. No. 6638, 658 U.N.T.S. Said documents are to be forwarded to the Central Authority of Japan as required by The Hague Convention, to wit: Hague Convention Division, Consular Affairs Bureau Ministry of Foreign Affairs, 100-8919 Kasumigaseki 2-2-1, Chiyoda-ku, Tokyo, Japan. Plaintiffs would further show that NSK, Ltd. engages in business in the State of Texas, but does not maintain a regular place of business or a designated agent for service of process in the State of Texas, and therefore, service of process is authorized under Section 17.044(b) of the Texas Civil Practice & Remedies Code by serving the Secretary of State of Texas as agent for NSK, Ltd. SUMMONS IS HEREBY REQUESTED.

II. <u>JURISDICTION AND VENUE</u>

- 7. This action was originally filed in Harris County, but was removed pursuant to 28 U.S.C. § 1332(a), on the basis of diversity of citizenship.
- 8. Harris County has jurisdiction over Defendants because at the time of the events in question they were doing business in Harris County, Texas, in a continuous and systematic way, and Plaintiff's claims arise out of Defendants' purposeful, specific contacts with the forum. Defendant ITC is at home in Harris County because their principal places of business are in Harris

County, Texas. Defendants Are also subject to jurisdiction in this Court due to their commission of a tort in Harris County, Texas. Tex. CIV. PRAC. & REM. CODE § 17.042(2). The subject matter in controversy is within the jurisdictional limits of this Court.

9. Venue is proper in Harris County, Texas because all or a substantial part of the events or omissions giving rise to Plaintiff's claims occurred in Harris County, Texas. TEX. CIV. PRAC. & REM. CODE § 15.002(a)(1).

III. FACTUAL BACKGROUND

A. The Incident.

- 10. INTERCONTINENTAL TERMINALS COMPANY LLC ("ITC"), own, operate and manage a massive bulk chemical storage facility at 1943 Independence Parkway on the Houston Ship Channel in Harris County, The ITC Facility is approximately 265 acres and at the time of the incident described below (the "ITC Incident") contained 242 tanks with a storage capacity of 13 million barrels. ITC receives and services its customers' products by ship, barge, pipeline, rail, and truck.
- 11. This lawsuit stems from a March 17, 2019 fire at the facility that occurred when butane was being injected into Tank 80-8 which contained Naphtha, a volatile substance used to create octane-boosting components for gasoline. Upon information and belief, high-pressure butane is used to get the chemical (naphtha) to rise to the top of the tank for transfer. The fire occurred when a pump seal failed on the Tank 80-8 manifold causing the butane to vaporize and ignite. The portion of the facility where the fire occurred contained 15 storage tanks in three rows of five. Tank 80-8 was located approximately in the middle of the tank farm. Notably, there was no foam fire suppression system in place and no access to dry chemical fire suppression or foam, which would have quickly extinguished the blaze. Therefore, the fire burned uncontrolled and spread to adjacent Tanks 80-2, 80-3, 80-5, 80-6, 80-11 and 80-13.

- 12. The fire continued to rage fueled by chemicals contained in the multiple storage tanks that were compromised by the fire and a dark black cloud of smoke engulfed the surrounding area for miles. Additional tanks caught fire, and approximately 11 tanks were actively burning and releasing air contaminants on March 18 through 19, 2019. The tanks contained gasoline blend stocks and components, such as, xylene, toluene and pyrolysis gasoline (which contains the carcinogen benzene). The fire was put out for several hours on March 20, 2019, but in the evening a tank re-ignited and was subsequently extinguished.
- 13. On March 21 and 22, 2019, benzene emissions caused by the damaged tanks resulted in a shelter-in-place for residents in Deer Park and La Porte and local school districts were closed. On multiple occasions air quality tests revealed Benzene and other volatile organic compound (VOC) readings in excess of the action levels set by the Occupational Safety and Health Administration (OSHA). In fact, an air monitoring report released by ITC revealed 51 benzene detections with an average concentration of 2.71 ppm, with a peak detection of 10.55 ppm near the intersection of Highway 225 and Independence Parkway on March 21, 2018.
- 14. In the afternoon of March 22, 2019, two tanks re-ignited sending another plume of black smoke into the air. Additionally, a containment dike surrounding the tanks collapsed resulting in the discharge of industrial waste and firefighting foam into a nearby ditch, and eventually Tucker Bayou and the Houston Ship Channel. The contents of the ditch ignited and burned for approximately an hour sending more black smoke and contaminants into the air.
 - 15. Plaintiffs were exposed to contaminants from the fire. They have suffered from

¹ To put this in perspective, OSHA has an "action level" for detection of benzene in an airborne concentration of 0.5 ppm calculated as an 8-hour time-weighted average. 1910.1028(b). The short-term exposure limit for benzene is set at 5 ppm, meaning that an employer must ensure that no employee is exposed to an airborne concentration of benzene in excess of 5 ppm as averaged over any 15 minute period. 1910.1028(c)(2).


significant health problems, including but not limited to: respiratory infections, headaches, nosebleed, coughing, scratchy eyes, insomnia, and shortness of breath as a result of breathing the toxic cloud released by Defendants. The specific health problems experienced by each individual plaintiff is detailed in that plaintiff's Short Form Complaint. Plaintiffs have all suffered injuries and damages as a proximate result of Defendants' negligent acts and omissions which resulted in the massive fire subject to this lawsuit.

B. The Investigation.


- 16. ITC's post-incident investigation revealed that, on December 4, 2018, ITC employees noticed that the Tank 80-8 pump was "unusually loud." A subsequent inspection of the pump determined that it was in need of new bearings. The pump was disassembled, and ITC's millwrights installed new NSK Model 5313 outboard bearings and NSK Model 6313 inboard bearings to support the pump's shaft. The remainder of the pump was then reassembled and placed into operation on the Tank 80-8 manifold.
- 17. On March 17, 2019, the NSK 5313 outboard bearing failed, causing vibrations within the impeller shaft that were directly transmitted to the mechanical shaft seal. This vibration loosened the bolted connections holding the mechanical shaft seal in place. Once the seal broke, the Naphtha escaped into the area around the Tank 80-8 pump, where it ignited and caused the incident.
- 18. When the Tank 80-8 pump was taken apart to determine the cause of the incident, investigators observed that the outboard bearing (constructed using NSK 5313 bearings) had come apart, resulting in loose bearing balls and ball remnants in the bearing house, meaning that at the time of the incident the outboard bearing was no longer capable of supporting the mechanical shaft centered in the bearing house. Most of these balls were severely deformed and/or fragmented.

19. A subsequent metallurgical examination revealed that the Model 5313 outward bearings contained unexplained internal voids, meaning they were not as durable as solid-core ball bearings and were more likely to fail. By contrast, the NSK 6313 inward bearings examined from the incident were solid throughout, as demonstrated by the below diagrams:

Cross Section of Nominally Intact NSK 5313 Ball Bearing from The Incident:



Cross Section of Nominally Intact NSK 6313 Ball Bearing from The Incident:



- 20. Upon information and belief, the design and specifications for the Model 5313 ball bearings did not call for internal voids, but instead called for solid core ball bearings. The internal voids were therefore a deviation from the intended specifications.
 - 21. Based upon information and belief, the NSK 5313 ball bearings were sold to ITC

by Defendant Allied Industrial Technologies, Inc.,

IV. <u>CAUSES OF ACTION</u>

COUNT I NEGLIGENCE AND GROSS NEGLIGENCE OF ITC

- 22. Plaintiffs incorporates by reference all preceding paragraphs as if fully stated herein and further states as follows:
- 23. The acts and omissions of Defendants constitute negligence and gross negligence, and separately and concurrently were a proximate cause of the incident upon which this suit is based, and of the injuries and damages suffered and sustained by Plaintiffs. The negligent acts and omissions of Defendants include the following:
 - a. Defendants failed to maintain equipment, including the Tank 80-8 manifold and seals;
 - b. Defendants failed to have in place a fixed foam fire suppression system for fire prevention, control or direct extinguishment of any flammable or combustible liquid fire within their tanks;
 - c. Defendants failed to have access to dry chemical and/or foam fire suppression materials to extinguish the fire after it started;
 - d. Defendants failed to adequately train workers regarding the hazards of injecting butane into tank manifolds;
 - e. Defendants failed to use ordinary care in developing and implementing a safety and fire prevention program;
 - f. Defendants failed to supervise and train workers to ensure that any safety guidelines in place would be enforced to protect against leaks when injecting butane into tank manifolds;
 - g. Defendants caused and permitted the release of volatile organic compounds and chemicals resulting in a continuous toxic cloud over La Porte, Deer Park and other parts of Harris County, Texas;

- h. Defendants failed to use ordinary care in monitoring the release of air contaminants and providing adequate warnings to the community of the release of volatile organic compounds and chemicals, including benzene;
- 24. Each of the foregoing acts and omissions, when taken separately or together, constitute negligence. Such acts were a direct and proximate cause of the injuries and damages sustained by Plaintiff.
- 25. The acts or omissions of Defendants involved an extreme degree of risk of which they had actual, subjective awareness of the risk involved, but nevertheless proceeded with conscious indifference to the rights, safety or welfare of others. Specifically, Defendants have a long history of incidents involving the release of toxic chemicals, as well as, citations and fines from regulatory agencies. Even after these events, at the time of this catastrophic fire, Defendants operated the facility with institutional ignorance or defiance to a culture of safety and accountability.
- 26. The forgoing actions and inactions of Defendants, and/or their respective employees or agents, whether taken separately or together, were of such a character as to constitute a pattern or practice of intentional wrongful conduct or malice resulting in the damages sustained by Plaintiff. These acts or omissions satisfy both the objective and subjective elements of gross negligence which is governed by V.T.C.A., Civil Practice & Remedies Code §§ 41.001(11), 41.003(a). Indeed, Defendants had actual awareness of the extreme degree of risk associated with the release of toxic chemicals and fires, and nevertheless proceeded with conscious indifference to the rights, safety, and welfare of Plaintiffs by failing to act to minimize or eliminate these risks. Therefore, Defendants are guilty of gross negligence for which they should be held liable in punitive and exemplary damages to Plaintiff.

COUNT II PRODUCTS LIABILITY

A. Manufacturing Defect - NSK Defendants.

- 27. Plaintiffs incorporate all preceding paragraphs as if fully set forth herein.
- 28. Defendants NSK Corp., NSK Ltd., NSK Precision, and NSK-AKS ("NSK Defendants"), are engaged in the business of manufacturing and placing into the stream of commerce the NSK 5313 bearings that caused the incident that is the subject of this litigation. As such, the NSK Defendants are "manufacturer[s]" as that term is defined by Section 82.011(4) of the Texas Civil Practice & Remedies Code.
- 29. NSK Defendants manufactured the NSK 5313 bearings and placed them into the stream of commerce with the expectation that those bearings would, and in fact did, reach the user or consumer without substantial change in the condition in which the bearings were sold.
- 30. A manufacturing defect exists when a product deviates, in its construction or quality, from the specifications or planned output in a manner that renders it unreasonably dangerous.
- 31. The NSK 5313 bearings, at the time they were placed into the stream of commerce by the NSK Defendants, were in a defective condition unreasonably dangerous to the end-user. Specifically, while the specification for the NSK 5313 bearings required that they contain a solid core, the bearings sold to ITC contained internal voids (*i.e.*, they had a hollow core) of approximately 0.33 inches. These internal voids caused the bearings to have a smaller diameter than would similar solid-core bearings, as well as an average mass of only 78% of the inboard bearing balls. This decreased size and mass caused the NSK 5313 ball bearings to deteriorate more

quickly than if they had a solid core, causing them to fragment and come loose within the bearing.

- 32. This fragmentation caused failure of the outboard bearing, which compromised resistance to thrust loading and generated the impeller shaft vibration that loosened the mechanical shaft seal and allowed the Naphtha to escape.
- 33. The failure of the outboard bearing, the vibration of the impeller shaft, the loosening of the mechanical shaft seal, and the release of Naphtha would not have occurred if the NSK 5313 ball bearings—like their NSK 6313 counterparts—were manufactured with a solid core in accordance with their design specifications. As such, this dangerous condition was a proximate cause of the March 17, 2019 explosion at ITC's Deer Park Facility and Plaintiff's injuries.

B. Design Defect - NSK Defendants.

- 34. Plaintiffs incorporate all preceding paragraphs as if fully set forth herein.
- 35. In the alternative, to the extent that the NSK 5313 ball bearings did not deviate from their design specifications, the NSK Defendants are liable for Plaintiff's injuries because the design of the 5313 ball bearings was defective. To recover for a products liability claim alleging a design defect, a plaintiff must prove that (1) the product was defectively designed so as to render it unreasonably dangerous; (2) a safer alternative design existed; and (3) the defect was a producing cause of the injury for which the plaintiff seeks recovery.
- 36. The NSK Defendants' design of the NSK Model 5313 ball bearing was defective because it contained "internal voids" that rendered the bearing unreasonably dangerous for its intended use. Rather than design the bearing with internal voids, the NSK Defendants should have utilized the solid-core design found in NSK Model 6313. That this "solid core" alternative design is safer than the "internal void" design of the NSK 5313 ball bearing is demonstrated by the fact that the NSK 5313 bearings deteriorated and fragmented while the solid-core NSK 6313 bearings

did not.

- 37. Similarly, the existence and utilization of the NSK 6313 ball bearings in the inboard bearing demonstrates that the solid core design is both technologically and economically feasible.
- 38. The "internal void" design was the producing cause of Plaintiff's injuries for the reasons discussed in paragraphs 39-41, *supra*. As such, the NSK Defendants are liable for Plaintiff's injuries.

V. CONTRIBUTORY NEGLIGENCE

39. Nothing Plaintiffs did or failed to do caused or in any way contributed to the cause of the occurrence in question. The injuries and damages complained of herein were proximately caused as a result of Defendants' respective conduct.

VI. DAMAGES

- 40. Plaintiffs would show that as a proximate result of the Defendants' negligence, they has suffered serious and disabling injuries, including the following:
 - a. Reasonable medical care and expenses in the past. These expenses were incurred by Plaintiffs for the necessary care and treatment of the injuries resulting from the accident complained of herein and such charges are reasonable and were usual and customary charges for such services in Harris County, Texas;
 - b. Reasonable and necessary medical care and expenses which will in all reasonable probability be incurred in the future;
 - c. Physical pain and suffering in the past;
 - d. Physical pain and suffering in the future;
 - e. Physical impairment in the past;
 - f. Physical impairment which, in all reasonable probability, will be suffered in the future;
 - g. Loss of earnings in the past;
 - h. Loss of earning capacity which will, in all probability, be incurred in the future;

- i. Disfigurement in the past;
- j. Disfigurement in the future;
- k. The cost of future medical monitoring;
- 1. Mental anguish in the past; and
- m. Mental anguish in the future.
- 41. By reason of the foregoing, Plaintiffs have been damaged in an amount far in excess of the jurisdictional limits of this Honorable Court. Plaintiffs make a claim for the above-mentioned damages and seek an amount within the jurisdictional limits of this Honorable Court. Additionally, as a result of the grossly negligent conduct of Defendants, Plaintiffs seek an award of exemplary damages.

VII. CONDITIONS PRECEDENT

42. All conditions precedent to Plaintiffs' claims for relief have been performed, have occurred, or have been waived.

VIII. PRE- AND POST-JUDGMENT INTEREST

43. Plaintiffs seek recovery of pre- and post-judgment interest at the maximum rate allowed by law.

IX. PRAYER

Plaintiffs respectfully request that Defendants be served with process, that they be required to appear and answer in this lawsuit, and that after a trial or other final hearing on the merits, the Court enter a judgment awarding Plaintiffs compensatory damages, as well as, costs, interest, or any other relief, monetary or equitable, to which Plaintiffs may be justly entitled.

Respectfully submitted,

TRACEY FOX KING WALTERS

By: /s/ Sean Patrick Tracey

Sean Patrick Tracey

Texas Bar No. 20176500

Shawn P. Fox

Texas Bar No. 24040926

Lance N. Walters

Texas Bar No. 24085639

stracey@traceylawfirm.com

440 Louisiana, Suite 1901

Houston, Texas 77002

Telephone: (713) 568-3518

PLAINTIFFS' CO-LEAD COUNSEL AND ATTORNEYS FOR VARIOUS PLAINTIFFS

ABRAHAM, WATKINS, NICHOLS, SORRELLS, AGOSTO & AZIZ

By:_/s/ Benny Agosto, Jr.

Benny Agosto, Jr.

Texas Bar. No. 00794981

Jonathan D. Sneed

Texas Bar No. 24085594

bagosto@awtxlaw.com

jsneed@awtxlaw.com

800 Commerce Street

Houston, Texas 77002

Tel. (713) 222-7211

Fax. (713) 225-0827

PLAINTIFFS' CO-LEAD COUNSEL AND ATTORNEYS FOR VARIOUS PLAINTIFFS

KENNEDY HODGES, L.L.P.

By: /s/ David W. Hodges

David W. Hodges

Texas Bar No. 00796765 4409 Montrose Blvd., Ste. 200 Houston, Texas 77006 Telephone: (713) 523-0001 dhodges@kennedyhodges.com

PLAINTIFFS' CO-LEAD COUNSEL AND ATTORNEYS FOR THE ARMSTRONG PLAINTIFFS

BRACEWELL LLP

By: /s/ Phillip L. Sampson, Jr.

Phillip L. Sampson, Jr. State Bar No. 00788344 Christopher L. Dodson State Bar No. 24050519 Carlton D. Wilde III State Bar No. 24093364 Shannon E. Glen State Bar No. 24109927 phillip.sampson@bracewell.com chris.dodson@bracewell.com cd.wilde@bracewell.com shannon.glen@bracewell.com 711 Louisiana, Suite 2300 Houston, Texas 77002 Tel. (713) 223-2300 Fax. (800) 404-3970

PLAINTIFFS' CO-LEAD COUNSEL AND ATTORNEYS FOR VOPAK TERMINAL DEEP PARK INC.